

Elcometer 116 Whirling & Sling Hygrometer



The Elcometer 116 Whirling and Sling Hygrometers are designed to determine the dew point and relative humidity (RH) at any given time.

The Elcometer 116A Whirling Hygrometer is available in Celsius scale. A guide for Relative Humidity (RH) determination is supplied with each instrument and the dewpoint can accurately be calculated using the Elcometer 114 Dewpoint Calculator.

The Elcometer 116C Sling Hygrometer, shown as the black unit in the photograph, is a convenient, self-contained instrument with an inbuilt slide rule for the calculation of %RH and dewpoint. This hygrometer has spirit filled thermometers and is available in °C or °F scales.

- Manual operation, no power supply required
- Spirit filled thermometers

Test Method and Operation

Hygrometers use a manual technique to measure Relative Humidity (RH) and dewpoint. These instruments consist of two thermometers, the bulb of one being covered by a wick. The wick is saturated by filling the plastic container with water. Hold the Hygrometer by the handle and whirl through 360° facing the wind or any airflow for about 90 seconds.

This is repeated until the wet bulb thermometer cools down to a constant frame temperature and two consecutive pairs of readings agree.

The RH and dewpoint are then calculated from the wet and dry bulb temperature readings using the Dew Point Table or the Elcometer 114 Dewpoint Calculator. Ensure the wet bulb wick dips into the small water container attached to the Hygrometer frame. Check the water level each time before using.

Technical Specification

Part Number	Description
G116A---1	Elcometer 116A Whirling Hygrometer - Metric °C
G116C---1	Elcometer 116C Sling Hygrometer - Metric °C
G116C---2	Elcometer 116C Sling Hygrometer - Imperial °F
Measuring Range	-5°C to 50°C
Dimensions	17 x 22mm
Weight	300g

Accessories

Part Number	Description
T1164441-	Elcometer 116A Spare Thermometer - °C
T11631224	Elcometer 116C Spare Thermometer - °C (Pack of 2)
T1164487-	Elcometer 116A Wicks (Pack of 5)
T13827259	Pure Distilled Water - 250ml
T1164479-	Elcometer 116C Spare Thermometer - °F
T11600212	Elcometer 116A Replacement Slide Rule
T11631168	Elcometer 116C Wicks (Pack of 4)
T13827494	Pure Distilled Water - 1000ml



Packing List

Elcometer 116A Whirling Hygrometer
Slide Rule Table
Operating Instructions
Elcometer 116C Sling Hygrometer
Slide Rule Table
Operating Instructions